

## Bond Projects Updates for Monday 10 June 2013

### Community Center

- Mechanical, electrical, and plumbing work continued.
- Cricket and parapet details finished up on the roof.
- Storefront window and door frames installation continued.

9' deep excavation for a sump pump outside the kitchen entry.  
(20130606-1019)



Housing for the sump pump, which provides flow assist when needed from the trash enclosure drain to the main sewer drain line.  
(20130606-1020)

This row of structural columns will be covered in finish panels to match the building exterior.  
(20130606-1026)





The row of columns with plywood under-cladding as seen from inside the Perera Pavilion. (20130606-1927)



Dance Studio and Perera Pavilion ceiling framing nearly completed. (20130606-1028)

#### Pleasant Oaks Park

- The Contractor, Goodland Landscape Construction, has taken possession of the site and grading work has begun.

