

Bond Projects Updates for Monday 12 August 2013

Community Center

- **MILESTONE:** Stucco scratch coat work began (first of three layers that comprise a stucco finish).
- Standing seam metal roofing materials staged on roof, while mockup awaits approval.
- Columns and framing for glass canopy were delivered to the site.



Heavy gauge steel framing for glass canopy. (20130807-0927)



Standing-seam metal roofing materials being staged on the roof.

(20130807-0924)

Part of the metal roofing mockup – protective film on the standing seams will be removed during installation.

(20130807-0941)





Bundles of metal roofing material are fastened to the roof with straps while awaiting installation.

(20130807-0945)

Workers mixing and applying the stucco scratch-coat on the west end of the building.

(20130809-1121)



Stucco scratch-coat being applied to the south wall of the facility offices. These windows overlook the playground.

(20130809-1125)

Pleasant Oaks Park

- Recycled (irrigation) water tie-in was accomplished.
- North parking lot – concrete curbs poured.
- Bioswale drain-rock installed, west end of north parking lot.
- Retaining walls are under construction.



Class 2 permeable drain rock in bioswale



Recycled water tie-in for irrigation



Footing for light pole

(view west up Hawthorne)

Irrigation piping and controller wiring



Constructing a retaining wall: Looking south along Monticello from a future entry into the parking lot.



Looking north along Monticello toward the existing sports building.
(POP materials provided by Lynn, Amanda, and Ginger.)