

Bond Projects Updates for Monday 20 May 2013

Community Center

- Mechanical , electrical, and plumbing installations continued.
- Roof framing and sheathing continued.



A look at the sheathing progress from the front. (20130516-0810)



A window mock-up ready for inspection in the west wall of the WeeTot Room. (20130516-0826)

Classroom window mock-up being inspected by Dahlin architects and a CSI project manager.

(20130516-0829)





Looking east from the corner of the southernmost classroom.

(20130516-0839)

Classroom on the left and "back doors" for the main hallway at center. The Dance Studio is on the far right.

(20130516-0840)



Falk Superintendent Nick Schmidt inspects a broken quick-coupler – it was repaired quickly, but not before the nearby Hackberry tree got a good watering.

(20130516-0848)




A worker cutting iron pipe for fire sprinkler system branch runs.

(20130516-0850)

Installation of HVAC ducting continues in the Perera Pavilion ceiling..

(20130516-0852)



A look at the sheathing progress at the main entry to the events area.

(20130516-0924)



Looking west from inside the Perera Pavilion through to the Dance Studio. (20130516-0853)



During the site tour at the weekly OAC (Owner/Architect /Contractor) meeting – details of roof finishing being discussed at the source. (20130516-0914)

Pleasant Oaks Park

- **GROUND-BREAKING:** Thursday 5/30/2013 at 4:00pm at the existing playground in Pleasant Oaks Park.